Universal Control 4.7.2 Milestone Release Notes

Oct 21, 2025

Version Information:

- Universal Control (Mac) - v4.7.2.108537
- Universal Control (PC) - v4.7.2.108537
- Universal Control (iOS/Android) - v4.7.2.108537
- QMix-UC (iOS/Android) - v3.5.0.106756
- Capture (Mac/PC) - v3.2.0.106606
- Quantum USB Firmware - v2.30.108533
- FaderPort 2018, 8, & 16 Firmware - v3.74
- ATOM - v3.52
- ATOM SQ - v1.17
- Revelator io44 Firmware - v1.22
- StudioLive Series III Ecosystem -
  - Series III Firmware - v3.2.0.108461
  - NSB Firmware - v2.0.0.107036
  - EarMix Firmware - v2.0.0.106950
  - AVB-D16 Firmware – v2.0.0.106920
  - SW5E Firmware - v1.5.0.92382

Supported OS Versions:

- macOS 12.4 (Monterey) or later
- Windows 10 (x64) 22H2 or later
- Windows 11 22H2 or later
- Android 8.0 (Oreo - only arm64-v8a) or later
- iOS 15.4 or later

New In This Release:

StudioLive Series III

- Performance improvements:
  - Memory optimized for improved stability
  - Improvement to the responsiveness of faders
  - Project/Scene recall response time improvements

Quantum ES / HD

- Quantum HD - Added "Pad" and "HPF" controls on ADAT input channels
- Quantum HD - Added the ability to stereo-link ADAT channels

Fixed In This Release:

Universal Control

- Fixed: Meters in Universal Control jitter when Series III mixer Channel Selection changes
- Fixed: Uninstaller moves Universal Control to Trash
- Fixed: [macOS Tahoe] Security Preferences open without any UC options listed

Series III

- Fixed: Renaming NSB or EarMix causes issues
- Fixed: “Update failed!” message displayed in UC despite successful firmware update
- Fixed: UC Batch Updater sometimes fails to update AVB-D16
- Fixed: [Windows] Firmware update progress window hangs after update
- Fixed: Ecosystem devices batch updates are reporting as failures or getting stuck during update

Quantum ES / HD

- Quantum HD - ADAT Controls grayed out with 2.23 firmware

Known Issues:

StudioLive Series III

- 64S - Mono Fader exponentially maxes out the level based on the placement of the Master Fader
- Sample Rate change not reported in Windows UC Launch Panel

Quantum ES / HD

- If the Primary unit is powered on first, the ADAT controls of the second or third unit may be unavailable until the ADAT units are power-cycled

ATOM SQ

- In Studio One Pro 7, pad(s) can blink erratically due to MIDI clock synchronization issue

Visit our Knowledge Base for more informative articles authored by the support staff.

To submit a support ticket or contact technical support, please log into your MyPreSonus user account.